

TOP SECRET**PRIORITY**

OUT62986

1967 AUG 30 23 20Z

P 302259Z
FM NPICAFSSO PACAF
AFSSO ACIC
AFSSO FTD
AFSSO USAFE
CNO

OPCEN

YSAKAKC

ZEM

TOP SECRET TTTT

REFERENCE: MISSION 1043

1. AN ANOMALY OCCURRED IN THE SCAN RATE OF THE FORWARD CAMERA (NO. 200) FIRST NOTICED IN PASS 68 AND INCREASING TO 40 PERCENT IN THE MIDDLE OF 1043-2. THE SCAN RATE VARIED OVER THE FRAME WITH THE GREATER ERROR AT THE SUPPLY END.

2. BECAUSE OF THE ERRONEOUS SCAN RATE, IMAGE SMEAR IS EVIDENT.

3. MENSURATION SHOULD BE MADE FROM THE AFT CAMERA AS THE VARYING SCAN RATE OF THE FORWARD CAMERA WILL SERIOUSLY AFFECT MEASUREMENTS MADE THEREFROM.

4. ON PASS 120 THE SCAN RATE WAS INCORRECT FOR BOTH THE AFT AND FORWARD CAMERAS, THEREFOR MEASUREMENT ACCURACY WILL BE AFFECTED.

GP-1

TOP SECRET

END OF MESSAGE

Declassification Review by NSA

SEC B1	
TDS	
CSD	
HD	
PD	
PSD	
PSD-ICB	
TID	25X1
IAO	
PAG	
DIAX-4	
SPAD	
NSA-LO	
DIA-AP	

25X1

25X1

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification